

# PRx Graphite

## Heat Molding Guide



### 1. Select Size & Rigidity

|          |             | Sm | Md | L | XL | XXL |
|----------|-------------|----|----|---|----|-----|
| Rigidity | Flexible    | X  | X  | X | X  | X   |
|          | Semi-Rigid  | X  | X  | X | X  | X   |
|          | Rigid       | X  | X  | X | X  | X   |
|          | Ultra-Rigid | X  | X  | X | X  | X   |



### 2. Heat the Shell

Heat in oven at 325°F for about 10 minutes.

For Ultra Rigid shells heat in oven at 350° for up to 15 minutes



In addition the shell can be spot heated if necessary.

\*Hold heat gun about 1 inch away from the shell.

### 3. Pressing Over Cast

Turn cast so the heel is in the back.

This will prevent the shell from shifting when the lid closes.



### 4. Finishing

Grind to the correct dimensions and heel cup depth.



PRx Graphite does not require special storage temperatures.